
## **30 Tonne Mono Strand Jack Flow Chart**

(mPa to Tonne)



PJM-30...-CHDA

mPa		Tonne
5	=	2.12
10	=	4.24
15	=	6.36
20	=	8.48
25	=	10.60
30	=	12.73
35	=	14.85
40	=	16.97
45	=	19.09
50	=	21.21
55	=	23.33
60	=	25.46
65	=	27.58
70	=	29.70



This Chart is for reference purpose only and based on theoretical values. The values given in this chart are nominal values only. Each Jack will give a different tonnages at stated pressures.

PJM Industrial always recommends that the Jacks be calibrated to determine exact loads.

PJM Industrial accepts no liability for any damage/improper results arising from the values in this chart.